

Serial No. 10/605,412
Filed: 09/29/04
Page 3 of 11

Examiner: Theresa T. Snider
Group Art Unit: 1744

Amendments to the Claims

Please amend the claims as shown below in the complete listing of claims.

Claims 1-10 (Cancelled)

11. (Currently Amended) A portable surface cleaning apparatus, comprising:

- a base housing adapted for movement along a surface to be cleaned;
- an upright handle pivotally mounted to the base housing;
- a liquid dispensing system comprising:
 - a liquid dispenser mounted on the base housing~~module~~ for applying liquid to a surface to be cleaned;
 - a liquid supply tank removably mounted to the handle or base housing for holding a supply of cleaning liquid;
 - a liquid supply conduit fluidly connected to the liquid supply tank and to the dispenser for supplying liquid to the dispenser;
 - a liquid recovery system comprising:
 - a recovery tank removably mounted on the base housing or handle and having a liquid recovery chamber for holding recovered liquid;
 - a suction nozzle mounted to ~~associated with~~ the base housing and adapted to draw dirty liquid from the surface to be cleaned;
 - a working air conduit extending between the recovery chamber and the suction nozzle;
 - a vacuum source in fluid communication with the recovery chamber for generating a flow of working air from the nozzle through the working air conduit and through the recovery chamber to thereby draw dirty liquid from the surface to be cleaned through the nozzle and working air conduit, and into the recovery chamber to thereby recover the dirty liquid from the surface to be cleaned;
 - an electrical cord mounted to the handle and connected to the vacuum source; and
 - upper and lower cord wraps in spaced apart, ~~axially aligned~~ relationship along a cord ~~wrap axis~~ on the handle for wrapping an electrical cord in a loop;

BEST AVAILABLE COPY

Serial No. 10/605,412
Filed: 09/29/04
Page 4 of 11

Examiner: Theresa T. Snider
Group Art Unit: 1744

the improvement comprising:

the electrical cord is mounted to the handle and projects from the handle in a direction in substantial ~~axial~~ alignment with the cord wrap axis and the at least one of the upper and lower cord wraps, and a strain relief collar mounted on the electrical cord at the handle and projecting from the handle in in a direction in substantial ~~axial~~ alignment with the the at least one of the upper and lower cord wraps along the cord wrap axis so that the electrical cord projects from the handle in a relatively straight line between the handle and the at least one of the upper and lower cord wraps.

12. (Previously Presented) A portable surface cleaning apparatus according to claim 11 wherein the strain relief collar is formed of an elastomeric material.

Claims 13-16 (Cancelled)

17. (Currently Amended) A portable surface cleaning apparatus according to claim 11 wherein the strain relief collar projects from the handle in in a direction along the cord wrap axis ~~axial alignment with the upper and lower cord wraps~~.

18. (Previously Presented) A portable surface cleaning apparatus according to claim 17 wherein the strain relief collar is mounted below the lower cord wrap and projects toward the upper and lower cord wraps.

19. (Currently Amended) A portable surface cleaning apparatus according to claim 11 wherein the strain relief collar is mounted below the lower cord wrap and projects toward the lower and upper cord wraps.

20. (Currently Amended) A portable surface cleaner comprising:
a base housing adapted for movement along a surface to be cleaned;
an upright handle pivotally mounted to the base housing;
a suction nozzle ~~associated with~~ mounted to the base housing and adapted to draw dirt from the surface to be cleaned;

Serial No. 10/605,412
Filed: 09/29/04
Page 5 of 11

Examiner: Theresa T. Snider
Group Art Unit: 1744

a vacuum source in fluid communication the suction nozzle for drawing air through the suction nozzle;

an electrical cord mounted to the handle and connected to the vacuum source; and
upper and lower cord wraps in spaced apart, ~~axially aligned~~ relationship along a cord
wrap axis on the handle for wrapping an the electrical cord in a loop

the improvement comprising:

the electrical cord is mounted to the handle at a location in substantial axial
alignment with the ~~upper and lower~~ cord wraps axis and projects from the handle in a direction in
substantial axial-alignment with at least one of the upper and lower cord wraps so that the
electrical cord projects from the handle in a relatively straight line between the handle and the at
least one of the upper and lower cord wraps.

21. (Previously Presented) A portable surface cleaner according to claim 20 and
further comprising a strain relief collar mounted on the electrical cord at the handle and
projecting from the handle toward the at least one of the upper and lower cord wraps.

22. (Previously Presented) A portable surface cleaner according to claim 21 wherein
the strain relief collar is formed of an elastomeric material.

23. (Previously Presented) A portable surface cleaner according to claim 21 wherein
the electrical cord is mounted below the lower cord wrap and projects toward both the upper and
lower cord wraps.

24. (Previously Presented) A portable surface cleaner according to claim 20 wherein
the electrical cord is mounted below the lower cord wrap and projects toward both the upper and
lower cord wraps.

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.